



THE MERSEY DOCKS & HARBOUR COMPANY

NOTICE TO MARINERS

No. 32A – 2007

PORT OF LIVERPOOL

BURBO BANK WIND FARM

AMENDMENT TO NOTICE TO MARINERS No 32 - 2007

NOTICE IS HEREBY GIVEN THAT WE HAVE BEEN NOTIFIED BY THE DEVELOPERS THAT THERE IS AN ERROR IN THE PERMANENT LIGHT PREVIOUSLY PROMULGATED IN NOTICE TO MARINERS No 32 – 2007 FOR TOWER BB 15. **THE PERMANENT LIGHT FOR BB-15 (ONLY) WILL DISPLAY THE FOLLOWING**
FL. Y. 2.5s 2M

CAPTAIN S.F. GALLIMORE
HARBOUR MASTER

24TH DECEMBER 2007